			•			
VISIBLE EMISSION NOT	ATIONS					
Inspector: Smel	KO				,	
Date of Inspection:	1 14					
0001	7 1 )	•				
Shift: (1st Shift or 2nd S	hift Ti	ime:				
	• •	3.,00				
Unit	Visual Inspection NORMAL Wor ABNORMAL			Comments		
Visible Emission From Shaker	nor					_
Visible Emission From Discharge Conveyor System	noR					

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

			•	
VISIBLE EMISSION NOT	ATIONS	-		
Inspector: Smello				
Date of Inspection:	K		7	
Sept	5/1	·		
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> S	hift Ti	ime: 5:100		
Unit	Visual Inspection		Comments	
	NORMAL, or ABNORMAL			
Visible Emission From Shaker	nor			
Visible Emission From Discharge Conveyor System	noR	, and the second		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

<b></b>			i e	
VISIBLE EMISSION NOT	ATIONS			
Inspector: Smell	Ö			
Date of Inspection:	0 10			
LOent	3,19	•		·
Shift: (1st Shift or 2nd Si	hift Ti	me:		
	• •	3 (00)		
Unit	Visual Inspection		Comments	
	NORMAL,			
	A'BNORMAL*			
Visible Emission From Shaker	noR	Comment		
Visible Emission From				
Discharge Conveyor System	nap	- American		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

7			•	
VISIBLE EMISSION NOT	ATIONS	•	-	
Inspector: Smell(0				
Date of Inspection:	1 101		<del></del>	
OCOT 1	_ [ ]			
Shift: (1st Shift) or 2nd S	hift Ti	ime: p		
		5.00		
and the control of th	Visual		Comments	menta 对于
	Inspection			的复数形式
	NORMAL.			
[44] [44] [44] [44] [44] [44] [44] [44]	grimor.			<b>全开始的</b> 在1
好物的時間的時間的學術的	ABNORMAL			
Visible Emission From Shaker	Mana			
	$  \eta u r  $	,,,,,		
Visible Emission From	10	,		
Discharge Conveyor System	1 1100	No.		
_				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS		•		
Inspector:					
OMEIFO					
Date of Inspection:	51,19				
Shift: 1 Shift or 2nd St	lift Ti	ime:			
	* *	5.0CJ			
Unit	Visual Inspection			Comments	
	NORMAL Culor A'BNORMAL				
Visible Emission From Shaker	NOR				
Visible Emission From Discharge Conveyor System	nor				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

·			•		
VISIBLE EMISSION NOT	ATIONS			•	
Inspector:	Contin	,			
Date of Inspection: 9/6//	41				
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> S	hift Ti	me: 500 f W			
Unit	Visual Inspection NORMAL Helor ABNORMAL		Comments		
Visible Emission From Shaker	Nov				
Visible Emission From Discharge Conveyor System	1/2/				

Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the

background.

	*		•	
VISIBLE EMISSION NOTA	ATIONS	•		
Inspector: Smell	6		]	
Date of Inspection:	7 101		1	
3001	417		_	
Shift: (1st Shift) or 2nd SI	hìft Ti	me:		
```		0.00		<del></del>
Unit	Visual	PRINCIPLE STREET	Comments	<b>数据的数据数据</b>
	Inspection			
The state of the second	NORMAL.			<b>经验证证明</b>
	or the contract of the contrac			
[4] 30数[30][5] [5] [5] [5] [5] [6] [6] [6] [6] [6] [6] [6] [6] [6] [6	A'BNORMAL	<b>建筑建筑设置的设计。</b>	· 是是是自己的一种,但是自己的特别,但是是一个人的一个人的一个人的一个人的。	<b>有点的情報包括在4</b> 。
Visible Emission From Shaker	nno			
4 .	170 K			
Visible Emission From	-			
Discharge Conveyor System	Lnan	-Methon		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS		·		
Inspector: Smelko	110110			•	
Date of Inspection: Sept	8 19			•	
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> Si	hift T	lme: 5,00			
Unit	Visual Inspection NORMAL ABNORMAL		.Comments		
Visible Emission From Shaker	nor	The Total Control of the Control of			
Visible Emission From Discharge Conveyor System	nor	National			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS				
Inspector: Smelfo					
Date of Inspection:	9,14			,	
Shift: (1 <sup>st</sup> Shift) or 2 <sup>nd</sup> S	hift Ti	me: SQ			
Unit	Visual Inspection NORMAL or ABNORMAL		Comment	is	
Visible Emission From Shaker	nor				
Visible Emission From Discharge Conveyor System	nor				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.


			•	
VISIBLE EMISSION NOT	ATIONS			
Inspector:	jelko			
Date of Inspection:	10.14		]	
Shift: (1st Shift or 2nd Si	hift Ti	ime: \$100	1	
Unit	Visual Inspection NORMAL Wor ABNORMAL		.Comments	
Visible Emission From Shaker	nor			
Visible Emission From Discharge Conveyor System	noo			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

	-					
VISIBL	.E.E	MISS	SION	NO	ГАТ	IONS

VIOIDEE EINIOOION NOTA	11010		<u> </u>
Inspector:	Smell	(O	
Date of Inspection:	Sept	11,14	·
Shift: 1st Shift or 2nd Sh	nift Ti	me: 5'.00	·
Unit	Visual Inspection NORMAL Or ABNORMAL		.Comments
Visible Emission From Shaker	nor		
Visible Emission From Discharge Conveyor System	nor		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOT	ATIONS			
Inspector: Smell	6			
Date of Inspection: Sept	13,14			
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> SI	nift Ti	ime: 5 00		
Unit	Visual Inspection NORMAL Or ABNORMAL		.Comments	
Visible Emission From Shaker				
Visible Emission From Discharge Conveyor System	nor			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

i i i i i i i i i i i i i i i i i i i			•		
VISIBLE EMISSION NOTA	ATIONS				
Inspector: Smelko					
Date of Inspection: Aug.	3.19			•	
Shift: (1 <sup>st</sup> Shift) or 2 <sup>nd</sup> Si	nift Ti	ime: 5 /00			
Unit	Visual Inspection NORMAL MORMAL ABNORMAL		.Comments		
Visible Emission From Shaker	nor				
Visible Emission From Discharge Conveyor System	noR				

• Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

• Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

				•		
VISIBLE EMISSION NOT	ATIONS					
Inspector: Smr \	6					
Date of Inspection:	14,19					
Shift: 1st Shift or 2nd S	hift T	ime: 5 0 V	1.			
Unit	Visual Inspection NORMAL			0	Comments	
	or ABNORMAL					
Visible Emission From Shaker	DOR		· · · · · · · · · · · · · · · · · · ·			
Visible Emission From Discharge Conveyor System	nol					

• Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

• Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS		•
Inspector: Smell	6		
Date of Inspection:			
	,		
Shift: (1 <sup>st</sup> Shift) or 2 <sup>nd</sup> Sh	nift Ti	me: 5100	
Unit	Visual Inspection NORMAL MINORMAL		Comments
Visible Emission From Shaker	nor.		
Visible Emission From Discharge Conveyor System	hon		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS				
Inspector: Smalko					
Date of Inspection:	16,19				
Shift: 1st Shift or 2nd Si	hift Ti	ime: 5.06		·	
Unit	Visual Inspection NORMAL WOOF ABNORMAL		.Comm	ents	
Visible Emission From Shaker	nor.				
Visible Emission From Discharge Conveyor System	nor				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

			*		
VISIBLE EMISSION NOT	ATIONS		-		
Inspector: Smelko					
Date of Inspection: <				·	
Sept	17.19	•			
Shift: 1 Shift or 2nd S	hift T	ime: 5:00			
LENGTH BELLEVILLE	Visual	diameter in the lighter	Comm	ients :	· (4) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1
	Inspection				
	NORMAL				
	P. Chords				
[14] 14 (14) [14] [15] [15] [15] [15] [15] [15] [15] [15	ABNORMAL	<b>一种企业的企业的企业的企业。</b>	· 特别是在自己的基本的。	鐵黑色物 中国电影员民民	"中心,并以"生"。清楚的,并由一个特殊的特殊的
Visible Emission From Shaker	nor				
Visible Emission From	11012				
Discharge Conveyor System		-			
Discharge Conveyor System	I NOR				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

<b>3</b>			•	
VISIBLE EMISSION NOTA	ATIONS	•		
Inspector: Smello				
Date of Inspection:	18,14			•
Shift: 1st Shift or 2td Si	hift Ti	ime: 5.60		
Unit	Visual Inspection NORMAL Wor ABNORMAL		.Comments	
Visible Emission From Shaker	hor	400000-		
Visible Emission From Discharge Conveyor System	nop	All Reservoir		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS	•		
Inspector: Smelko		•		
Date of Inspection:	19,14			
Shift: (1st Shift) or 2nd SI	nift O Ti	ime: 5,00PM		
Unit	Visual Inspection NORMAL PROPERTY ABNORMAL		Comments	S NE
Visible Emission From Shaker	nor			
Visible Emission From Discharge Conveyor System	nor			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS	·	_		
Inspector:	d Canton				
Date of Inspection:	1140				
Shift: 1st Shift or 2nd Sl	hift Ti	me: SAM			
Unit	Visual Inspection NORMAL Helora ABNORMAL		Comment	S	
Visible Emission From Shaker	N.				
Visible Emission From Discharge Conveyor System	1)		gasting direction.		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS			
	impiton.			
Date of Inspection: 3/21	114			
Shift: 1st Shift or 2nd Sl	hift Ti	me: SAM		
Unit	Visual Inspection NORMAL TOT ABNORMAL		.Comments	
Visible Emission From Shaker	Nav			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS					
Inspector: Sme 16		•				
Date of Inspection: Sept	22,14				•	
Shift: 1st Shift or 2nd S	hift Ti	Ime: 5.00				
Unit:	Visual Inspection NORMAL NORMAL ABNORMAL		.Comm	ents		
Visible Emission From Shaker	nor	ation <sub>top</sub>				
Visible Emission From Discharge Conveyor System	nor					

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS		
Inspector: Smello			
Date of Inspection:	22 11		
UCOI	<u> </u>	•	
Shift: (1st Shift) or 2nd S	hift Ti	Ime:	,
	· ·	9,00	
Unit	Visual Inspection NORMAL		Comments
	ABNORMAL*		
Visible Emission From Shaker	noR	type (Titler)	
Visible Emission From			
Discharge Conveyor System	nor		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS				,	
Inspector:	upt on					
Date of Inspection: 9/24/	19					
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> Sl	hift Ti	me: 500 A1				
Unit:	Visual Inspection NORMAL TOT ABNORMAL			Commen	l <b>ts</b>	
Visible Emission From Shaker						
Visible Emission From Discharge Conveyor System	No./	A 'management gastrassy Anleggy June dennesse and the second	I			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS	
Inspector: Ted Compton	
Date of Inspection: 9/25/14	
Shift: 1st Shift or 2nd Shift Time: 5,00 A M	
Unit Visual Inspection NORMAL HOURT ABNORMAL	Comments
Visible Emission From Shaker	
Visible Emission From Discharge Conveyor System	

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS			·	
1	ed Campton				
Date of Inspection:	6/14				
Shift: 1st Shift or 2nd Si	nift Ti	ime: SOAM			
Unit:	Visual Inspection NORMAL MORMAL		Comment	S	
Visible Emission From Shaker	Nov	A commence of the commence of			
Visible Emission From Discharge Conveyor System	0/0/				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.


VISIBLE EMISSION NOTA	ATIONS			,	
Inspector: Ted C	ampton.				
Date of Inspection: 9/27	114		-	•	
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> SI	nift Ti	me: 500 AM			
Unit	Visual Inspection <u>NORMAL</u> STORMAL ABNORMAL		Comments		
Visible Emission From Shaker	Nor.				
Visible Emission From Discharge Conveyor System		what the transport of the contract of the cont			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

· VI:	SIRI	FF	พเรร	ION	NOT	'ATIO	NS

AIOIDEE EINIOOIOM MOTA	110.110			
Inspector: Smelk	)			
Date of Inspection:	<u></u>			
200	21.14			•
Shift: (1st Shift) or 2nd SI	hift Ti	ime:		
	• •	5.60		
Unit	Visual Inspection NORMAL		Comments	
	ABNORMAL*			
Visible Emission From Shaker	nor			
Visible Emission From		,		
Discharge Conveyor System	non			
	101			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOT	ATIONS	•			
Inspector:	1. tevini				
Date of Inspection:	3/14		<del></del>		
Shift: 1st Shift or 2nd S	hift Tim	e: 560AM			
Unit	Visual Inspection NORMAL Proof		Comm	nents	
Visible Emission From Shaker	Nor	· · · · · · · · · · · · · · · · · · ·			
Visible Emission From Discharge Conveyor System	No				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS			
Inspector:	inter.			
Date of Inspection: 9/29/	W/		_	
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> Si	hift Ti	ime: 1500AM		
Unit:	Visual Inspection NORMAL FOR		Comments	
Visible Emission From Shaker	/.	e-gazorofiles/Septiminational and high grounds yet and the second processing and the second proc		
Visible Emission From Discharge Conveyor System	No		gentlege tillge skille skille som	

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOT	ATIONS			
Inspector:	Constitut.			
Date of Inspection: $9/30$	14			e de la companya de
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> S	hift Ti	ime: 560AW		
Unit	Visual Inspection NORMAL TOO ABNORMAL		.Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	No	,		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.